


Toyota LandCruiser Replacement Parts

<http://landcruiser.makers.com.tw>

Email: carparts.tw@gmail.com



Land Cruiser Oil Pan Seal

TOYOTA OEM Part Number	Model
11213-38010, 11213-35010	22R
12151-30010	12R
12151-33010	6R,7R,8R,16R,18R
12151-35010	22R
12151-38010, 12151-35010	18R, 20R
12151-44010	5R
12151-47011	H, HU
12151-54010/11	2L
12151-54020/30	2L, 2L-T, 3L-T
12151-54050	3L
12151-56010/20	2B, 13B
12151-58030	11B, 14B
12151-60010	F, 2F
12151-61011, 12151-60020	F, 2F, 3F
12151-65020	B, 2B
12151-68010, 12151-68011	2H
12151-71020	2Y, 3Y, 4Y
12151-75020	1RZ

**Please feel free to contact us,
If you don't find what you need, Thank you**
<http://landcruiser.makers.com.tw> Email: carparts.tw@gmail.com